


Pulsating Pressures Measured at Measuring Point V1, without valve


Fig. 2

BEST AVAILABLE COPY



Pulsating Pressures Measured at Measuring Point V1, pulsation frequency adjusted to 7 Hz

FIG. 3

BEST AVAILABLE COPY

Pulsating Pressures Measured at Measuring Point V1, Pulsation Frequency
adjusted to 20 Hz

Fig. 4

BEST AVAILABLE COPY




Fig. 5

BEST AVAILABLE COPY

Fig. 6

